



MAZDA
CLUB

TECHNICAL SECTIONS

AVAILABLE ON CD, ON USB FLASH DRIVE, BY EMAIL AND IN PRINTED FORMATS

Reprints from the 1998 thru 2022 MC ONLYWAY

PUBLISHED BY THE MC
5433 N. ASHLAND AVE., CHICAGO, IL 60640 U.S.A.
Phone: 773-769-7396

email: info@mazdaclub.com
website: www.mazdaclub.com



MAZDA CLUB TECHNICAL SECTIONS

<u>PUBLICATION</u>	<u>PAGE</u>	<u>PUBLICATION</u>	<u>PAGE</u>
Volume 11	9	Volume 34	68
Volume 11, Number 2	13	Volume 35	69
Volume 12, Number 2	17		
Volume 13	21		
Volume 13, Number 2	22		
Volume 14	25		
Volume 15	28		
Volume 15, Number 2	31		
Volume 16	33		
Volume 17	37		
Volume 17, Number 2	41		
Volume 18	42		
Volume 18, Number 2	45		
Volume 19	46		
Volume 20	48		
Volume 20, Number 2	50		
Volume 21	52		
Volume 22	54		
Volume 22, Number 2	55		
Volume 23	56		
Volume 24	57		
Volume 25	58		
Volume 26	59		
Volume 27	60		
Volume 28	61		
Volume 29	62		
Volume 30	63		
Volume 31	65		
Volume 32	66		
Volume 33	67		

NOTE: Please note the ads that may appear here are reproduced as they originally appeared in that issue and therefore may be several years old and are not to be relied on for prices or information.

Nothing may be reproduced in whole or in part without the express written consent of the publisher. The views of contributing writers are their own and not necessarily the views of the MC. Readers are warned in following any advice given and no liability either express or implied is assumed by the advice or opinions given by individual contributors or the MC.

ARTICLE INDEX

Publication references in which MC publication the article originally appeared and the year; the page number it was on and if a Question and Answer (Q & A), its position on the page and page number in this issue.

SUBJECT/ <u>ARTICLE</u>	ORIGINAL PUBLICATION		PAGE NUMBER	
	<u>ISSUE</u>	<u>PAGE</u>	<u>Q & A</u>	<u>THIS ISSUE</u>
Carburetion/Fuel System				
Flooded	Volume 11, Num 2	17	2	15
Hi-octane gas	Volume 19	14	2	46
RX-7 flooding	Volume 24	12	1	57
Starting a flooded RX-7	Volume 14	17		27
Shutter valve	Volume 16	15	3	34
Cooling and Heating Systems				
AC compressor	Volume 18	15	4	43
AC not working	Volume 18	15	5	43
Choke failing	Volume 13, Num 2	15	4	22
Heater blower not working	Volume 18, Num 2	14	4	45
Heat problems	Volume 21	14	2	52
Overheating	Volume 15, Num 2	18	1	32
Radiator cap hissing	Volume 18, Num 2	14	2	45
Running hot	Volume 11	20	3	9
Electrical				
Alarm light	Volume 18	14	12	42
Armed alarm	Volume 12, Num 2	18	1	20
Battery drainage	Volume 15, Num 2	17	1	31
Battery tender	Volume 35	14	3	69
Brake lights	Volume 14	15	3	25
Code meaning	Volume 18	14	3	42
Daytime running lights disable	Volume 33	14	1	67
Door open light	Volume 18, Num 2	14	1	45
Fuse link problem	Volume 21	14	1	52
Fuse on Protege	Volume 35	14	2	69
Fuse removal	Volume 17	14	3	37
Headlight bulb	Volume 20	14	5	48
LED lights install - MX-5	Volume 34	14	4	68
Lights turning on	Volume 13, Num 2	16	2	23
MX-6 short	Volume 25	12	1	58
Overhead door lights	Volume 32	14	3	66
Power window problem - Miata	Volume 31	14	3	64
Reset engine light	Volume 17	14	2	37
Trailer connections	Volume 17, Num 2	14	1	41
Windshield wipers	Volume 19	14	3	46
Engine/Mechanical				
Apex seals replacement - RX-8	Volume 34	14	3	68
Brake caliper	Volume 20	15	1	49

SUBJECT/ ARTICLE	ORIGINAL PUBLICATION		PAGE NUMBER	
	ISSUE	PAGE	Q & A	THIS ISSUE
Beeping sound	Volume 16	14	3	33
Belt replacement	Volume 18	15	4	43
Changing spark plugs	Volume 18	15	2	43
Check engine light	Volume 13, Num 2	16	4	23
Check engine light pt. 2	Volume 14	16	2	26
Check engine light pt. 3	Volume 18	14	1	41
Check engine light pt. 4	Volume 20, Num 2	14	1	50
CPU replacement	Volume 13, Num 2	16	1	23
Cruise control	Volume 16	15	1	34
Engine cutting out	Volume 21	14	5	52
Engine dies	Volume 13, Num 2	16	3	23
Engine miles	Volume 18, Num 2	14	3	45
Engine warm up	Volume 22, Num 2	12	1	55
Fuel filter location	Volume 14	15	1	25
Idle adjustment	Volume 16	15	4	35
Idle problems	Volume 13, Num 2	15	3	22
More rotary engine power	Volume 17	15		38
Motor mount adjustment	Volume 14	16	3	26
Not starting	Volume 16	14	1	33
Rattle	Volume 14	15	5	25
Rotary engine failure	Volume 11	20	1	9
Rotary failure	Volume 27	12	1	60
Remanufactured rotary eng,	Volume 12, Num 2	18	2	20
Slow idle	Volume 26	12	1	59
Spark plug spark	Volume 28	12	1	61
Starting after storage	Volume 18	16	1	47
Starting problems - CX-5	Volume 31	14	1	64
Starting problems - Mazda 6	Volume 34	14	1	68
Stops accelerating	Volume 20	14	1	48
Stutters on acceleration	Volume 20, Num 2	14	2	50
Thermostat replacement	Volume 13, Num 2	15	5	22
Timing belt	Volume 22, Num 2	12	2	55
Tribute stalling issue	Volume 15, Num 2	17	2	31
Valve train noise	Volume 13	17	1	21
Vibration	Volume 22	14	2	54
Warm start	Volume 11, Num 2	17	1	15
Won't start	Volume 17	14	1	37
Exterior/Body				
Car cover	Volume 33	14	2	67
Convertible top replacement	Volume 32	14	1	66
Headlights yellow	Volume 22	14	3	54
Item to get great paint	Volume 29	12		62
Paint chipping on Mazda 6	Volume 33	14	3	67
Rust on doors - CX-5	Volume 34	14	2	68

SUBJECT/ ARTICLE	ORIGINAL PUBLICATION		PAGE NUMBER	
	ISSUE	PAGE	Q & A	THIS ISSUE
Gauges				
Oil light	Volume 14	16	4	26
Temperature gauge	Volume 15, Num 2	17	3	31
Temperature gauge red	Volume 18	14	3	42
General				
'65 Mazda coupe	Volume 17, Num 2	14	4	41
Breathable cover	Volume 18	15	3	44
Car Storage	Volume 11	24		11
Collectors Ratings	Volume 15	14		28
Insuring your classic car	Volume 11, Num 2	6		13
Mazda B2300 truck power	Volume 35	14	1	69
Mazda EV at Disney World	Volume 35	14	4	69
More power	Volume 13	17	2	21
Outside cover	Volume 17, Num 2	14	5	41
Owner's manual	Volume 15	16	2	29
Running faster	Volume 13	17	3	21
RX-7 packages	Volume 30	12	3	63
Venom 400 system	Volume 15	16	1	29
Interior				
Radio surround	Volume 22, Num 2	12	3	55
Seat belt	Volume 14	16	1	26
Wet carpet	Volume 15	16	4	29
Oil/Lubrication				
Dirt on oil	Volume 12, Num 2	8		17
Gear oil	Volume 11	20	2	9
Mysteries of motor oils	Volume 16	16		35
Oil metering pump	Volume 13, Num 2	15	1	22
Suspension/Handling/Braking				
Creaking noise	Volume 14	16	5	26
CV joint replacement	Volume 13, Num 2	16	5	23
Master Cylinder caps	Volume 36	14	5	69
Shock mounting holes	Volume 17, Num 2	14	2	41
Suspension replacement	Volume 28	12	2	61
Tires/Wheels				
Aftermarket wheels	Volume 11, Num 2	17	4	15
Biggest tire	Volume 16	15	2	35
Performance tires	Volume 15	17	1	30
Tire balancing	Volume 24	12	2	57
Tire replacement	Volume 17	14	5	37
Tire size	Volume 11	21		10

SUBJECT/ <u>ARTICLE</u>	ORIGINAL PUBLICATION			PAGE NUMBER	
	<u>ISSUE</u>	<u>PAGE</u>	<u>Q & A</u>	<u>THIS ISSUE</u>	
Transmission/Clutch/Drive Train					
1-2 shift violent shifting	Volume 32	14		2	66
Axle ratios	Volume 15	16		3	29
Clutch disengaging	Volume 22	14		1	54
Clutch frozen	Volume 16	14		2	33
Clutch problems - Mazda 3	Volume 31	14		2	64
Manual transmission oil	Volume 32	14		4	66
Rear end gear	Volume 21	14		3	52
Shift slippage	Volume 15	16		5	29
Transmission flush	Volume 14	15		2	25
Transmission slipping	Volume 17	14		4	37
Transmission surging	Volume 14	15		4	25
Throttle sensor	Volume 13, Num 2	15		2	22